

FIG. 1





FIG. 2

A perspective view of a mechanical assembly 5000. The assembly includes a base plate 5002 and a top plate 5006. A central component 5003 is positioned between them, featuring two parallel rollers 5004 and 5005. A drive mechanism at the bottom left consists of a gear 5010 meshed with a smaller gear 5011, which drives roller 5004 via a shaft 5013. Roller 5005 is driven by a similar mechanism with gear 5020 and shaft 5021. Various other parts are labeled with reference numerals: 5001, 5007, 5008, 5009, 5010, 5011, 5012, 5013, 5014, 5015, 5016, 5017, 5018, 5019, 5020, 5021, 5022, 5023, 5024, 5025, 5026, 5027, 5028, 5029, 5030, 5031, 5032, 5033, 5034, 5035, 5036, 5037, 5038, 5039, 5040, 5041, 5042, 5043, 5044, 5045, 5046, 5047, 5048, 5049, 5050, 5051, 5052, 5053, 5054, 5055, 5056, 5057, 5058, 5059, 5060, 5061, 5062, 5063, 5064, 5065, 5066, 5067, 5068, 5069, 5070, 5071, 5072, 5073, 5074, 5075, 5076, 5077, 5078, 5079, 5080, 5081, 5082, 5083, 5084, 5085, 5086, 5087, 5088, 5089, 5090, 5091, 5092, 5093, 5094, 5095, 5096, 5097, 5098, 5099, 5100.

FIG. 3



09482872.011400

FIG. 4





FIG. 5


PROBLEM TYPE	INTERNET ADDRESS (WEBSITE URL)	PROBLEM CODE	NATURE OF PROBLEM	ANSWERS
A	NONE	105	PAPER LOADED ?	OUT OF PAPER.
A	NONE	106	HEAD NOT MOUNTED ?	HEAD IS NOT MOUNTED.
A	NONE	107	COVER LEFT OPEN	COVER IS OPEN.
A	NONE	108	PAPER JAM	REMOVE JAMMED PAPER.
A	NONE	109	NO INK	OUT OF INK.
B	http://www. design. service. co. jp	110	5V NORMAL ?	NO 5V DC. TAKE PRINTER TO SERVICE DEPOT.
B	http://www. design. service. co. jp	111	V _M (MOTOR VOLTAGE) NORMAL ?	NO MOTOR VOLTAGE. TAKE PRINTER TO SERVICE DEPOT.
B	http://www. design. service. co. jp	112	V _H (HEAD VOLTAGE) NORMAL ?	NO HEAD VOLTAGE. TAKE PRINTER TO SERVICE DEPOT.
B	http://www. design. service. co. jp	113	T _φ (AMBIENT TEMPERATURE) NORMAL ?	PRINTER TEMPERATURE IS ABNORMAL. TAKE PRINTER TO SERVICE DEPOT.
B	http://www. design. service. co. jp	114	T _H (HEAD TEMPERATURE) NORMAL ?	HEAD TEMPERATURE IS ABNORMAL. TAKE PRINTER TO SERVICE DEPOT.
C	http://www. customer. service. co. jp	115	QUESTION CONCERNING PAPER	"AN APPROPRIATE ANSWER TO YOUR INQUIRY CORRESPONDING TO THIS PROBLEM CODE WILL BE PROVIDED BY THE PROGRAM AVAILABLE AT YOUR CUSTOMER DEPOT"
C	http://www. customer. service. co. jp	116	QUESTION CONCERNING SPECS	
C	http://www. customer. service. co. jp	117	REGARDING PRODUCT INQUIRIES	

FIG. 6



09462672-011400

FIG. 7



09462672.011400

FIG. 8




FIG. 9

